



CIP CID #1834

Instructions

Acidified Rinse

STEP
1

- Blend a solution of 1 to 2 oz. per 5 gallons of Water.

STEP
2

- Circulate for 15-20 minutes at a temperature of 80°- 140°F.

STEP
3

- Hose Rinse.

STEP
4

- Sanitize to Local Codes.

Recommendations for Optimal Performance

- Utilization of acidified rinse is key after each caustic cycle to minimize caustic film which may cause foaming
- Utilization of acidified rinse is key after each caustic cycle to minimize the buildup of beer stone

Sales@stone-leigh.com
StoneLeighbrewcleaners.com
@stoneleighbrewcleaner
508-465-0230